



31 CENTRAL DRIVE, ANDREWS,  
GOLD COAST, QUEENSLAND, 4220  
PHONE: (07) 5593 8533  
FAX: (07) 5593 6938  
ABN: 53 010 410 447

ALL PARTS AND ENGINES HAVE A 7 TO 90 DAY WARRANTY PERIOD. THE ONLY EXCEPTION TO THIS IS A MAZDA ROTARY ENGINE, WHICH HAVE A START UP WARRANTY PERIOD ONLY. UNLESS OTHER WISE STATED IN WRITING.

**IMPORTANT – WARRANTY PERIOD COMMENCES FROM DATE OF PURCHASE.**

**ANY ALTERATIONS TO THIS WARRANTY MUST BE OBTAINED IN WRITING AT TIME OF PURCHASE.**

IN THE EVENT THAT THERE IS SIGN OF A MALFUNCTION IT IS THE END USERS RESPONSIBILITY TO CEASE OPERATING THE VEHICLE AND REPORT THE PROBLEM TO ROLIN AUTOMOTIVE IMPORTS (07 5593 8533) OR YOUR SUPPLIER.

FAILURE TO COMPLY WITH THIS REQUEST MAY RESULT IN MORE SERIOUS DAMAGE AND JEOPARDISE YOUR WARRANTY ENTITLEMENT.

IT IS THE PURCHASERS RESPONSIBILITY TO RETURN THE VEHICLE OR ENGINE TO THE PLACE OF PURCHASE; FREIGHT PAID, SO THAT AS ASSESSMENT OF THE CLAIM CAN BE CARRIED OUT.

ROLIN AUTOMOTIVE IMPORTS CANNOT TAKE RESPONSIBILITY FOR ANY WARRANTY CLAIM NOT ASSESSED BY ROLIN AUTOMOTIVE IMPORTS OR ITS AUTHORISED AGENT.

FAILURE TO COMPLETE PROPER MAINTENANCE OF AN ENGINE AND A CHECK OF OIL & FUEL LEVELS WILL NULL AND VOID THIS WARRANTY.

IMPROPER APPLICATION OR INSTALLATION. E.G. CHANGE OF SUMP - NEW GASKET MUST BE FITTED OR NO WARRANTY CLAIM CAN BE CONSIDERED THROUGH OIL FAILURE. UNAUTHORISED REPAIRS OR DISMANTLING OF ENGINE WILL VOID WARRANTY.

ROLIN AUTOMOTIVE IMPORTS DO NOT COVER UNDER WARRANTY ANY ENGINE FITMENT NOT CARRIED OUT BY ROLIN AUTOMOTIVE IMPORTS OR AN AUTHORISED FITTING AGENT.

ALL ENGINES ARE PRE-TESTED BEFORE LEAVING OUR PREMISES EG: COMPRESSION, OIL PRESSURE.

ROLIN AUTOMOTIVE IMPORTS WILL NOT BE RESPONSIBLE FOR WARRANTY CLAIMS WHERE FAILURE WAS CAUSED BY:

1. **OVERHEATING - ALL ENGINES ARE HEAT TAPED - THIS MUST NOT BE REMOVED OR WARRANTY IS VOID.**
2. **CAM BELT FAILURE - IT IS RECOMMENDED THAT BELT BE REPLACED AT THE TIME OF FITMENT OF ENGINE.**
3. **A FULL SERVICE MUST BE DONE WHEN ENGINE IS FITTED AND ALL RECORDS OF PARTS AND SERVICES KEPT, AS THESE WILL BE REQUIRED TO SUPPORT YOUR WARRANTY CLAIM.**
4. **OIL FAILURE. OIL LEVELS, PRESSURES AND SEALS ARE TO BE CHECKED/REPLACED AT THE DIGRESSION OF THE FITTER.**

ALL RADIATORS MUST BE PROFESSIONALLY CLEANED OUT AND THERMOSTAT REPLACED.  
OIL LEAKS WILL NOT BE COVERED. SEALS ARE TO BE REPLACED AT THE FITTERS DIGRESSION.

ALL ACCESSORIES TO ENGINES ARE SUPPLIED FREE OR CHARGE AND ARE NOT COVERED BY WARRANTY E.G. ALTERNATOR, WATER PUMP, TURBO, FLYWHEEL AS THESE ITEMS CANNOT BE TESTED BY US IN THE FINAL APPLICATION.

THE FITMENT OF SOME ACCESSORIES MAY BE IN BREACH OF AUSTRALIAN A.D.R. RULES SO IT IS STRONGLY RECOMMENDED THAT ALL AUSTRALIAN ACCESSORIES ARE FITTED E.G. CARBURETTOR, EXHAUST, INJECTORS AND FUEL PUMPS. (DIESEL)

WHERE A CLAIM IS WARRANTED ROLIN AUTOMOTIVE IMPORTS OR ITS AUTHORISED AGENT WILL REPAIR OR REPLACE THE DEFECTIVE PART OR ENGINE AT OUR COST UPON THE AUTHORISATION OF THE OWNER IN WRITING BUT TAKE NO RESPONSIBILITY FOR THE COST OF REMOVAL OR FITMENT IF NOT FITTED BY ROLIN AUTOMOTIVE IMPORTS.

WE WILL NOT BE HELD RESPONSIBLE FOR ANY DOWN TIME, LOSS OF PROFITS OR CONSEQUENTIAL DAMAGE OR LOSS ASSOCIATED WITH THIS CLAIM.  
ANY PERFORMANCE ENGINE OR PARTS BEING USED FOR OTHER THAN NORMAL ROAD USEAGE WILL NOT BE CONSIDERED FOR WARRANTY CLAIMS. WARRANTY IS VOIDED IF ENGINE OR TRANSMISSION IS USED/FITTED OTHER THAN AS PER MANUFACTURER'S SPECIFICATIONS.

**NO REFUNDS OR EXCHANGES ON ELECTRICAL/ELECTRONIC ITEMS.**  
**THIS DOES NOT AFFECT THE STATUTORY RIGHTS OF THE CUSTOMER.**